

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-3216	DATE	May 18, 2021
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	A possible problem to the side stand bracket. In particular, when the motorcycle is placed on the side stand, it may happen in some rare cases that the bracket deforms as a result of repeated stress due to its load and, in exceptional situations, even breaks, causing the motorcycle to fall. If the side stand bracket is broken, it could damage the side stand sensor switch, resulting in an engine stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-GA01	XDiavel, XDiavel S	2016	311
EBL-GA01	XDiavel, XDiavel S	2017	32
		TOTAL	343