

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4959	DATE	May. 20. 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Rear reflector may have internal surface molded into incomplete form due to inadequate control over reflector molding conditions. Such a reflector can bring about scattering of reflected light, thereby not complying with Article 38 (Standards for Rear Reflectors) of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-NC56	「CBR400R」 「400X」	2020-2021	1,959
2BL-RH03	「CBR650R」 「CB650R」	2020-2021	1,597
2BL-PC60	「Rebel 500」	2020-2021	520
TOTAL			4,076

## THOSE DELIVERED AS “REPLACEMENT/SERVICE PARTS”

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS
REFLEX REFLECTOR	33741-KPL-902	2020～2021	131
TOTAL			131