

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3220	DATE	May 21 2021
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	The transmission oil cooler (TOC) hose may have been manufactured with incorrectly cured rubber. An incorrectly cured TOC hose may have a weakened hose wall that can rupture, allowing transmission fluid to leak. Transmission fluid leaking from a TOC hose may contact a competent ignition source and lead to a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-KL20L	「Cherokee」	2021	1
		TOTAL	1