

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4958	DATE	May. 25. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain emission control devices, due to the improper assembly of the NOx sensor wiring installed upstream and downstream SCR catalyst, the wiring installed upstream and downstream of the catalyst may be connected in reverse order. Therefore, emission control devices may not function properly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-PR1APJF	[-]	2019~2020	31
		TOTAL	31