## 

CAMPAIGN No.	4962	DATE	May.26th 2021	
MANUFACTURER	NIPPON SHARYO.LT	D.		
DESCRIPTION	NO.1			
OF DEFECT	On tank vehicles, due to inappropriate construction of the rear-frame,			
	the vibration is brought by the vehicle running, so the cracks may occur			
	on the joint of the rear-frame and the tank-sub-frame and so on.			
	If the vehicles are continued to run without the repairing, the cracks			
	turns out and it may become to be lost the stability for the vehicles run			
	NO.2			
	On tank vehicles, due to inappropriate construction of the tire			
	chain-box bracket, the vibration is brought by the vehicle running, so			
	the cracks may occur on the chain-box bracket and so on.			
	If the vehicles are continued to run without the repairing, the cracks			
	turns out, and the tire chain-box and the bracket may break down, so			
	block the other traffics	S.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ATL135LNG	LNG tank -semi-trailer	ATL135LNG-1~3 Nov. 30 2008~Jan. 22 2009	3
ATL140LNG		ATL140LNG-1 Aug. 8 2006	1
KTL141LNG		KTL141LNG-1∼60 Aug. 3 2011∼Nov. 30 2016	58
BTL140LNG		BTL140LNG-1 $\sim$ 25 Feb. 14 2017 $\sim$ Feb. 11 2021	25
KTL143LNG		KTL143LNG−1∼4 Nov.29 2007∼Mar.1 2011	4
KTL148LNG		KTL148LNG-1∼4 Jul.9 2012∼Mar.12 2015	4
BTL148LNG		BTL148LNG-1 Dec. 1 2018	1
KTL150LNG		KTL150LNG-1~21 Nov. 28 2007∼May. 30 2011	20
KTL157LNG		KTL157LNG-1∼9 Sep. 30 2014∼Nov. 8 2016	9
BTL157LNG		BTL157LNG-1∼7 Nov.9 2017∼Mar.29 2019	7
KTL160PR	LPG tank -semi-trailer	KTL160PR-7~34 Oct. 24 2011~Nov. 27 2015	28
BTL160PR		BTL160PR-1∼10 Dec.11 2017∼Mar.31 2021	10
		TOTAL	175

(Caurtion) The range of vehicle base numbers for vehicles that are recalled may include vehicles that are not eligible.