

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4961	DATE	May.26.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the high pressure fuel pump of the subject vehicles, due to insufficient pressure resistance performance of the components against fuel pressure, the inside of the pump may be worn or damaged over time during operation. If this were to occur, stress is concentrated on the welded portion of the pump, which could cause cracks at the weld and lead to a fuel leakage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-NRE210	[COROLLA]	2019-2021	417
3BA-NRE210H	[COROLLA SPORT]	2018-2021	13,293
3BA-NRE214H		2018-2021	3,694
3BA-NRE210W	[COROLLA TOURING]	2019-2021	1,024
3BA-NGX10	[C-HR]	2019-2021	2,954
3BA-NGX50		2020-2021	1,064
		TOTAL	22,446