

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 9 6 0	DATE	May. 27. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the steering knuckle, due to improper heat treatment in the manufacturing process, so the steering knuckle strength decreases and improper wheel alignment may occur. Therefore, if a large force is applied during use, it may be deformed, and in the worst case, it may be broken and then the vehicle might not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
5BA-RV37	N I S S A N S K Y L I N E	2 0 2 0	433
5AA-HV37			84
5AA-HNV37			41
4BA-Z34	N I S S A N F A I R L A D Y Z		70
5BA-Y51	N I S S A N F U G A		58
5BA-KY51			43
5BA-KNY51			19
5AA-HY51			38
5AA-HGY51	N I S S A N C I M A		16
4BA-R35	N I S S A N G T - R		101
		TOTAL	903