

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4963	DATE	1. Jun. 2021
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some speedometers have a needle retaining pin that is different from the specified pin. Therefore, when the temperatures inside the speedometer ASSY increase, the paint on the surface of the retaining pin becomes sticky, and in the worst case, the needle may be stuck to the retaining pin and the speedometer may become inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-DG32J	tricker XG250	2020	374
TOTAL			374

Something shipped as a replacement repair part and for which the assembled vehicle cannot be identified.

PART NAME	PART NUMBER	MODEL YEAR PART	NUMBER OF PART
METER ASSEMBLY	5XT-83500-20	2020~2021	103
TOTAL			103

Vehicles with replacement repair parts assembled shall be subject to the same improvement.