

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3230	DATE	June 2 nd , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to an incorrect seat assembly rework process, the screw connection of the seat belt catch may not be tightened properly. Thus, customer may perceive a rattling noise in the bolting area. In the worst case, the function of the restraint system may be impaired and increase the risk of injury in case of an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-5F20	BMW 320i	2020	3
3DA-5V20	BMW 320d xDrive	2020	1
3BA-5F20	BMW 330i	2020	1
3DA-6L20	BMW 320d xDrive Tr.	2020	6
3BA-6K20	BMW 320i Touring	2020	2
		TOTAL	13