

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3222	DATE	June 3, 2021
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, welding spatter produced inside the high pressure fuel pump due to incorrect weld cord position may block the fuel pressure control valve. This may cause warning light turning on, engine not start and/or not enough power.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-P21HN05	208	2020	148
5BA-P24HN05	2008	2020	2
	TOTAL		150