

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3223	DATE	June 3, 2021
MANUFACTURE	DS Automobiles (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, there was incomplete soldering inside headlight auto-adjustment unit. The incomplete soldering degrades over time and may cause open circuit which may result in warning light coming on and no function of headlight auto adjustment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-D34HN05	DS 3 Crossback	2020	61
	TOTAL		61