

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4965	DATE	June 8, 2021
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the heavy-duty truck's engine manufacturing process, due to inappropriate tightening of engine components fixing bolts/nuts, bolts/nuts may become loose by vehicle vibrations. If the vehicle continues operation under these conditions, depending on loosing part, the engine may have coolant water, exhaust gas and/or fuel leakage which may cause engine performance deterioration. In the worst case scenario, the vehicle might have a risk of an engine overheat or a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK5AAB	Quon	2020	1	
		Total	1	