Import Vehicles

CAMPAIGN No.	GAL-3232	DATE	2021/06/08	
MANUFACTURER	Tesla, Inc.			
MANUFACIURER	(Japanese Importer; Tesla Motors Japan)			
DESCRIPTION OF DEFECT	The driver and front-passenger shoulder belt portion of the seat belt system is attached to the b-pillar through a top loop. Specifically, the top loop is attached to an actuating bracket with a secured fastener, and the actuating bracket is attached to the b-pillar with another secured fastener. During assembly, the fastener securing the actuating bracket to the b-pillar may not have been secured to correct specifications.			

Туре	Commercial name	MODEL YEAR RECALLED	Number of Vehicle
ZAA-3L13	Model 3 RWD	2019	4
ZAA-3L23	Model 3 AWD	2019	1
ZAA-3L23P	Model 3 AWD	2019	12
Total	3 kinds	2019	17