

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 9 7 0	DATE	Jun. 10. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding bolts for engine mount brackets, the bolt may come loose due to improper mounting method. If the driver continues to drive in this condition, the engine unit may be tilted after bolts broken, and then the engine unit beats at the front suspension member and it leads to noise. In the worst case, the drive shaft may come off and the vehicle may not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6AA-E13	N I S S A N N O T E	2 0 2 0	26,754
6AA-SNE13		~ 2 0 2 1	567
		TOTAL	27,321