

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3234	DATE	June 10. 2021
MANUFACTURER	JOHN DEERE (Japanese Importer:YANMAR AGRIBUSINESS CO.,LTD.)		
DESCRIPTION OF DEFECT	Some bearing cap bolts on the crankshaft of agricultural tractors have insufficient tightening torque due to improper programming of the tightening tool. Therefore, if the engine is used as it is, the bolts loosen due to engine vibration or the like, and in the worst case, the engine is damaged and the vehicle is not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「JD-6195R」	2020	1	
	「JD-6215R」	2020	2	
		TOTAL	3	