

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4969	DATE	June 11, 2021
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	As the oil seal performance of the brake master cylinder is inappropriate, the oil for boosting may flow to the brake oil side. And, when brake operation is used a lot, the brake oil may heat expand and the volume of brake oil expands. Therefore, the brake oil may leak from the reserve tank if the truck continues to be used as it is.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-D4K	FD40PXII	2015 - 2017	9
XDN-D4L	FD45PXII FD50PXII	2015 - 2016	12
YDN-D4N	FD35PXIII FD40PXIII	2017 - 2019	10
YDN-D4P	FD45PXIII FD50PXIII	2018 - 2020	10
		TOTAL	41