

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4967	DATE	June 15, 2021
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the fuel devices of internal-combustion engine forklift and shovel loader vehicles, there are cases where strength of injector body is insufficient due to improper manufacturing process. There is a possibility that repeated common rail pressure (fuel pressure) may cause cracks at the inlet of the injector, and lead to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A8FDL18	TOYOTA GENE0	2018 - 2020	83
YDN-A8FDL25		2017 - 2020	224
YDN-A8FDL30		2018 - 2020	5
YDN-A8FD18		2018 - 2020	14
YDN-A8FD25		2018 - 2020	115
YDN-A8FDJ35		2017 - 2020	136
		TOTAL	