

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3237	DATE	June 15 <sup>th</sup> , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing control process, uncoated bolts may have been installed in the timing chain. This may lead to elongation of the timing chain, and as the elongation progresses noise may occur. If the noise is not noticed or ignored, the timing chain may break in extreme case, which may cause engine damage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-1S20	BMW 118d	2016	11
LDA-2E20	BMW 218d Gran Tourer	2016	24
LDA-8C20	BMW 320d	2016	33
LDA-FW20	BMW 523d	2016	1
LDA-MX20	BMW 523d touring	2016	2
LDA-WY20	BMW X3 xDrive 20d	2016	9
LDA-KS30	BMW X5 xDrive 35d	2016	10
LDA-LR20	MINI Cooper D Clubman	2016	8
LDA-LR20	MINI Cooper SD Clubman	2016	3
LDA-XT20	MINI Cooper SD 5 Door	2016	1
LDA-XN20	MINI Cooper SD	2016	1
LDA-XD20F	MINI Cooper D Corossover	2016	7
LDA-XD20A	MINI Cooper D Corossover A4	2016	5
LDA-ZB20	MINI Cooper SD Corossover	2016	6
<b>TOTAL</b>			<b>121</b>