

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3239	DATE	June 15, 2021
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing control process, uncoated bolts may have been installed in the timing chain. This may lead to elongation of the timing chain, and as the elongation progresses noise may occur. If the noise is not noticed or ignored, the timing chain may break in extreme case, which may cause engine damage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FDA-3P10	D3 Biturbo	2017	2
		TOTAL	2