

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4983	DATE	June 17, 2021
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the heavy-duty truck with leaf suspensions, due to the inappropriate software program of vehicle master control unit which controls automatic headlamp vertical adjustment function, when the lighting switch is at the position lamp on + AUTO head lamp position, the automatic headlamp vertical adjustment is not functioning. Thus, the vehicle is not fulfill Safety Regulation for Road Vehicles Article 32 regarding headlamps.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CG5CL	Quon	2021	1	
		Total	1	