

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4977	DATE	June 24, 2021
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In the steering gear, due to improper sealing of the boot mounting area and its location, which is directly beneath the drain hose of the air conditioner, the condensed water from the air conditioner may drip onto the mounting area and enter inside the gear.</p> <p>Therefore, if a vehicle with this condition is continuously used, rust may generate inside the gear and cause abnormal noises. In the worst case, the bearing may be damaged and the steering may not be controllable.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S321V	HIJET	2017-2019	76,564
HBD-S321V			
EBD-S331V			44,652
HBD-S331V			
EBD-S321W	HIJET DECKVAN		2,064
EBD-S321W			3,048
ABA-S321G	ATRAI WAGON		6,887
ABA-S331G			4,411
EBD-S321B	SAMBAR		4,319
HBD-S321B			
EBD-S331B			4,138
HBD-S331B			
EBD-S321Q	SAMBAR OPENDECK	31	
EBD-S321Q		74	
ABA-S321N	DIAS	411	
ABA-S331N		554	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S321M	PIXIS VAN	2017-2019	8,323
HBD-S321M			
EBD-S331M			4,959
HBD-S331M			
		TOTAL	160,435