

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	GAI-3173	DATE	June 25, 2021
MANUFACTURE	Indian Motorcycle Polaris Japan Inc		
DESCRIPTION OF DEFECT	<p>Gear position sensor internal resistance of gear position switch is improperly set, an inaccurate gear number signal is transmitted due to resistance value cannot be detected correctly, and the meter may display the wrong number of gears. Therefore, the gear was shifted to any position, in spite of the neutral is displayed, and in the worst case, the driver may mistakenly recognize the neutral and fall.</p> <p>All vehicles replace gear position switches with updated product. Also inspect the shift drum pin and spring and replace them with new ones if they are damaged.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
A	Chief	2014~2019	231
C	Chief Classic		
CC	Chief Dark Horse		
CCC	Chief Vintage		
CCD	Chieftain		
CCV	Chieftain Classic		
CV	Chieftain Dark Horse		
D	Chieftain Elite		
T	Chieftain Limited		
TC	Roadmaster		
TCA	Roadmaster Classic		
TH	Roadmaster Elite		
THA	Springfield		
TR	Springfield Dark Horse		
TRA			
Unknown			
		TOTAL	231