

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

### Domestic Vehicles

CAMPAIGN No.	4986	DATE	July 5, 2021
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF	<p>Due to inappropriate fixing of wirings for rear combination lamps, wires can hang down in some of the vehicles equipped with a tail lift. In that case, wires may contact the exhaust pipe and get damaged, which may cause the driver's side rear combination lamps not to turn on. Therefore, those vehicles are likely to fail to conform to articles 37 (standards for tail lamps), 39 (standards for brake lights), 40 (standards for reverse lights), 41 (standards for turn signals) and 41-3 (standards for hazard warning lamps) of safety regulations for road vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBF-SQ2F24	「ATLAS」	2021	2
		TOTAL	2