

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4987	DATE	July.7.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On the idling stop and start system vehicles, due to combination of improper programming of the idling stop and start system and insufficient heat insulation of the battery, if the vehicle is continuously operated with high temperature of the battery caused by the long idling, the refresh charging for the deterioration control could become insufficient, causing the abnormal deterioration of the battery. If this were to occur, the engine may not re-start after an idling stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AGH30W 3BA-AGH30W	[ALPHARD] [VELLFIRE]	2017-2021	5,002
DBA-AGH35W 3BA-AGH35W			25,745
DBA-GGH30W 3BA-GGH30W			14,367
DBA-GGH35W 3BA-GGH35W			5,869
			TOTAL