

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4990	DATE	July. 8. 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Headlights may have allowed soldering flux to remain on the surface of the contacts of the high beam/low beam switch due to a structural fault in the contacts of the high beam/low beam switch. Such headlights can suffer contact failure of the high beam/low beam switch, which could, in the very worst case, cause the high beams to fail to come on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MC51	「CBR250RR」	2017-2021	13,835
2BL-SD04	「CRF1000L Africa Twin」	2017-2019	2,055
EBL-SD04		2016	1,765
2BL-SC77	「CBR1000RR」	2017-2020	1,356
2BL-SC80	「CB1000R」	2018-2020	1,207
2BL-PC60	「Rebel 500」	2020-2021	520
EBL-SC68	「GOLD WING F6C」	2014-2016	229
		TOTAL	20,967