VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3248	DATE	July. 8. 2021		
MANUFACTURER	Thai Honda Manufacturing Co., Ltd.				
DESCRIPTION OF DEFECT	Headlights may have allowed soldering flux to remain on the surface of the contacts of the high beam/low beam switch due to a structural fault in the contacts of the high beam/low beam switch. Such headlights can suffer contact failure of the high beam/low beam switch, which could, in the very worst case, cause the high beams to fail to come on.				

TYPE	COMMERCIAL	MODEL YEAR		NUMBER OF
	NAME	RECALLED		VEHICLE
2BK-MC49	「Rebel 250」	2019-2021		15,828
2BK-MF13	「FORZA」	2018-2020		6, 592
			TOTAL	22,420