

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4992	DATE	July 15 ,2021
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	With regard to the automated manual transmission in some light duty trucks, sealability of the oil hose is insufficient due to inappropriate operation in its manufacturing process. This may cause oil to leak from the joint of the said hose and the oil pipe, making the transmission inoperative, and in the worst case, making the vehicles undrivable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NHR88A 2RG-NHR88AN	[ELF]	2021	68
2RG-NHS88A 2RG-NHS88AN		2021	22
2RG-NJR88A 2RG-NJR88AD 2RG-NJR88AN		2021	117
2RG-NJS88A 2RG-NJS88AN		2021	35
2PG-NKR88N 2PG-NKR88R 2RG-NKR88A 2RG-NKR88AD 2RG-NKR88AN 2RG-NKR88AR 2RG-NKR88N 2RG-NKR88R		2021	93
2PG-NKR88YN		2021	4
2PG-NKS88AD 2PG-NKS88AN 2RG-NKS88A		2021	7
2RG-NLR88AN 2RG-NLR88AR 2RG-NLR88N 2SG-NLR88AN		2021	189
2RG-NLS88AN 2RG-NLS88AR		2021	6
2RG-NMR88AN 2RG-NMR88AR 2RG-NMR88N 2RG-NMR88R		2021	98

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-NMS88AN 2PG-NMS88AR 2RG-NMS88AN 2RG-NMS88AR	[ELF]	2021	21	
2RG-NNR88AR 2RG-NNR88N		2021	3	
2RG-NNS88AN		2021	2	
2PG-NPR88AN 2PG-NPR88N 2RG-NPR88AN 2RG-NPR88AR 2RG-NPR88N 2SG-NPR88AN		2021	77	
2PG-NPR88YN 2RG-NPR88YN		2021	29	
2PG-NPS88AN 2PG-NPS88AR 2RG-NPS88AN 2RG-NPS88AR		2021	21	
2RG-AHR88A 2RG-AHR88AN		[ATLAS]	2021	10
2RG-AHS88A 2RG-AHS88AN			2021	5
2RG-LHR88A 2RG-LHR88AN	[TITAN]	2021	12	
2RG-LHS88A 2RG-LHS88AN		2021	5	
2RG-LKR88AD		2021	1	
2RG-LLR88AN		2021	3	
2RG-LMR88AR 2RG-LMR88R		2021	2	
2RG-LPR88AN 2RG-LPR88AR		2021	4	
2PG-LPS88AR		2021	1	
			TOTAL	835

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Oil Hose	8-97488088-2	2021	1
	8-98389804-1	2021	2
	8-98488347-0	2021	1
		TOTAL	4