

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4993	DATE	July 21, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to insufficient control in the manufacturing process, the inner diameter of the fuel hose connecting the fuel pump and the fuel injector was improper.</p> <p>Therefore, the connecting part of the fuel hose may lose airtightness, the fuel pressurized by the fuel pump may leak from the insufficient airtightness part.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-CH41A	BURGMAN	2018-2020	2,338
		TOTAL	2,338