

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4994	DATE	July.30, 2021
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the impeller (resin impeller) of the fuel pump, since the molding conditions are inappropriate, the resin density may be low, and it may swell and deform with the fuel. Therefore, when the impeller comes in contact with the pump case, the fuel pump becomes malfunctioning, and in the worst case, there is a risk of engine stalling during running.		

Subaru	DBA-VM4	「Levorg」	2018~2019	6,348
	DBA-VMG		2018	1,626
	DBA-VAG	「WRX」	2018	1,891
	DBA-SJG	「Forester」	2018	666
	DBA-ZC6	「BRZ」	2018	820
Toyota	DBA-ZN6	「86」	2018	3,108
			TOTAL	14,459