Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3260	Date	July. 29, 2021			
Manufacturer		Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited				
Description of defect	manufactured. The outer rubber hose The hose may sp time. A split hose engine bay, run of the road surface.	The fuel return hose assembly may have been incorrectly manufactured. The reinforcing yarn mesh between the inner a outer rubber hose layers may not provide adequate reinforcer. The hose may split when pressure pulsations flex the hose of time. A split hose will allow low pressure fuel to leak into the engine bay, run down the cold side of the engine and flow on the road surface. Inspect the hose assembly and renew if required.				

Туре	Commercial name	Model	year recalled	Number of vehicles
3CA-DC2NC	F-PACE			27
3CA-DF2NB	E-PACE			23
3CA-JA2ND	XE	2021	6	
3CA-JB2ND	XF		24	
3CA-JBS2ND	XF Sport Brake		12	
3CA-LC2ND	Discovery Sport			62
3CA-LY2NAC	Danies Davas Valas		9	
3CA-LY2NCC	Range Rover Velar		34	
3CA-LZ2NB	Range Rover Evoque			18
			Total	215

(JIS A4 size)