

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4 9 9 1	DATE	July 30, 2021
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>In the exhaust system of a road roller, the strength of the exhaust pipe mounting bracket is insufficient, there is what the bracket is broken.</p> <p>Therefore, if the exhaust pipe is used as it is, the exhaust pipe fixing clamp may be broken or the exhaust pipe may be cracked due to vibration during traveling, and in the worst case, the exhaust pipe may fall to the lower part of the vehicle frame.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「SW504」	2018 — 2021	87
TOTAL			87