
VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4996	DATE	August 4, 2021	
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan			
DESCRIPTION OF DEFECT	In the drive shaft of the powder carrier tank pressurizing compressor, as the design of the mounting bracket for fixing the center bearing which connects the drive shafts was not appropriate, the fuel tank of the vehicle and the mounting bracket may come in contact with each other. If the unit is continued to be used in this state, there is a possibility that the fuel tank may be damaged, and therefore leak in the worst case.			

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HINO	2DG-FS1EHA		2019	1
	2KG-FS1EHG	HINO PROFIA	2019-2020	4
	2PG-FR1EHG		2019	1
	2KG-FR1EHG		2019-2020	3
			TOTAL	9

(日本産業規格A列4番)