

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3274	DATE	August 24 th , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to improper programming of the engine ECU, there is a possibility that the engine could shortly turn backwards when the engine start process is interrupted. When the engine turn shortly backwards, internal components of the vacuum pump can be damaged. If this were to occur, loss of braking assist while driving could increase the vehicle stopping distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-5U30	BMW M340i xDrive	2019 - 2021	1,055
3BA-6N30	BMW M340i xDrive Touring	2019 - 2021	195
3BA-12AR30	BMW M440i xDrive Coupe	2020 - 2021	310
	BMW M440i xDrive Cabriolet	2020 - 2021	65
3BA-JS30	BMW 540i xDrive	2019 - 2021	124
3BA-JT30	BMW 540i xDrive Touring	2019 - 2021	41
3LA-7D30	BMW 745e	2019 - 2021	191
3LA-7W30	BMW 745Le xDrive	2019 - 2021	16
3BA-TY30	BMW X3 M40i	2019 - 2021	197
3BA-2V30	BMW X4 M40i	2019 - 2021	224
3BA-HF30	BMW Z4 M40i	2018 - 2019	472
3BA-HF30T		2019 - 2021	205
TOTAL			3,095