

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3275	DATE	Aug.24.2021
MANUFACTURER	BMW (TOYOTA)		
DESCRIPTION OF DEFECT	In the engine ECU of the subject vehicles, due to improper programming, there is a possibility that a force in the reverse rotation direction could be applied to the engine by operation such as engine stop immediately after engine start and the lubricating oil in the vacuum pump could flow backwards, causing damage to components of the vacuum pump. If this were to occur, loss of braking assist while driving could increase the vehicle stopping distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-DB02	[SUPRA]	2020-2021	672
3BA-DB42		2019-2020	2,069
		TOTAL	2,741