

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5001	DATE	Aug.26 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For electrical wire harness of street sweepers, the wire coating may be melted by the heat of the engine exhaust manifold due to improper wire routing of the starter motor wiring of the work engine. Therefore, if the wiring is continued to be used as it is, the core wire may be exposed and short-circuited, or in the worst case, the wire coating may ignite resulting in a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
2PG-FE2ABA	RANGER	2019~2021	11	
LDG-FE7JGAA 改		2017	1	
TOTAL			12	