

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5010	DATE	Sep. 3, 2021
MANUFACTURER	SHO-SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	<p>Due to inappropriate circuit design of the crop-dusting vehicles, an overcurrent may flow to the starter switch. Therefore, the resin inside the starter switch may melt, resulting in poor contact between the contacts, and in the worst case, the engine may stop and not be able to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-J7	「3S-FSC600TLG」	2016-2016	19
		2016-2019	68
	「3S-FSC1000TLG」	2016-2020	87
		TOTAL	174