

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 0 0 7	DATE	Sep. 9. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the headlight, the optical axis might not have been inspected and adjusted correctly due to a communication failure in the optical axis inspection equipment of the vehicle production plant. Therefore, the optical axis may not comply with regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-CS4E26	N I S S A N N V 3 5 0 C A R A V A N	2 0 1 9	1
LDF-CW8E26		~	1
CBA-KS2E26		2 0 2 0	5
CBF-VR2E26			1
LDF-VW2E26			4
LDF-VW6E26			3
		TOTAL	15