

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5011	DATE	Sep. 9, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The oil seal lip may be everted in the manual shift lever shaft of the automatic transmission, due to the use of improper assembling jig at the time of the production. As the result, ATF may leak from the oil seal and the vehicle could be immobilized in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
HBD-DA17V	EVERY	2021	308	A/T Vehicles only
EBD-DA17V			40	
3BA-DA17W			97	
3BA-JB64W	JIMNY		137	
3BA-JB74W			78	
HBD-DR17V	NV100 CLIPPER		226	
EBD-DR17V			41	
3BA-DR17W	NV100 CLIPPER RIO		98	
HBD-DG17V	SCRUM		77	
3BA-DG17W			18	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
HBD-DS17V	MINICAB	2021	62	A/T Vehicles only
EBD-DS17V			18	
3BA-DS17W	TOWNBOX		10	
		TOTAL	1,210	