## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN No.	Gai-3281	DATE	September 9 <sup>th</sup> , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fault involves the plug connection from the wiring harness, which supplies power to the blower controller for the air conditioner. Due to inappropriate material of the plug connection coating, this may deteriorate due to friction corrosion caused by high current flow and vehicle vibration.  This can lead to overheating of the plug connection and subsequently to melting. In very rare cases, this can lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FE30	BMW X5 3.0 si	2007 - 2010	2,694
ABA-ZV30	BMW X5 xDrive 35i	2010	81
ABA-ZV30S		2010	354
DBA-ZV30		2010 - 2011	97
DBA-ZV30S		2010 - 2011	413
ABA-FE48	BMW X5 4.8i	2007 - 2010	236
ABA-ZV44	BMW X5 xDrive 50i	2010 - 2011	27
ABA-ZV44S		2010 - 2011	7
ABA-GY44	BMW X5M	2009 - 2011	42
ABA-FG30	BMW X6 xDrive 35i	2008 - 2010	619
ABA-FG35		2010	152
DBA-FG35		2010 - 2011	142
ABA-FG44	BMW X6 xDrive 50i	2008 - 2011	112
ABA-GZ44	BMW X6M	2009 - 2011	59
		TOTAL	5,035