

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	5019	DATE	September 17, 2021
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the heavy-duty trucks, due to the inappropriate LED front fog lamp sub-harness routing, vehicles with the FUPD (Front Under-run Protection Device) variant which has smallest gap between the FUPD and the fog lamp may have the connector interference with the FUPD and/or may be caught by the FUPD. Thus, if the vehicle continues operation under these conditions, by vehicle vibrations the connector may become broken which may cause contact failure, disconnection or short-circuit and the fog lamp might become unlighted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5BL	Quon	2021	1	
2PG-CG4CA			3	
2PG-CG5CA			56	
2PG-CG5CE			6	
2PG-CG5CL			6	
2PG-CW5AL			41	
2PG-CW5BL			5	
2PG-CX5BA			2	
2PG-CX5BL			1	