

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5017	DATE	22. Sep. 2021
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding some speedometers of the SR400, the nut used for connecting the gear unit on the front wheel and the speed transmission cable is not tightened properly. Therefore, if the speed transmission cable continues to be used under this condition, the connecting nut may become loose and the cable may come off, and as a result, the speedometer and the odometer may stop working.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-RH16J	SR400	2021	81
		TOTAL	81