

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5018	DATE	Sep.22.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>#1. In an emergency calling system, due to an improper program of data communication module, there is a possibility that mutual conversion between voice data and communication data may not be possible. In this condition each other's voice cannot be heard in an emergency situation, resulting in noncompliance with the requirement prescribed in "Safety Regulations for Road Vehicles", Article 43-8 (requirement of accident emergency call system).</p> <p>#2. In a hybrid system, due to an improper programming in the hybrid vehicle control ECU, the ECU might incorrectly detect an abnormality when the shift position is changed during the calculation of the shift range. If this occurs, warning lights would illuminate and the hybrid system would shut down resulting in loss of the motive power while driving.</p> <p>#3. In exhaust manifold for gasoline engine of the subject vehicles, due to insufficient consideration of strength when the welding condition of the exhaust manifold pipe was changed, there is a possibility that stress, such as temperature cycling and vibration during vehicle use, could develop a crack at the welded portion of the pipe. If this were to occur, exhaust gas could leak during engine high revolution driving such as hill-climbing, resulting in noncompliance with a certain emission standard.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-KSP210	[YARIS]	2021	7,439	#1
5BA-MXPA10			3,145	
5BA-MXPA15			1,246	
6AA-MXPH10			8,583	
6AA-MXPH15			798	
5BA-MXPB10	[YARIS CROSS]	2021	5,564	#1
5BA-MXPB15			1,564	
6AA-MXPJ10			8,338	
6AA-MXPJ15			2,443	
4BA-GXPA16	[GR YARIS]	2021	411	#1
5BA-MXPA12			261	
6AA-AXUH80	[HARRIER]	2021	4,520	#1
6AA-AXUH85			1,684	
6BA-MXUA80			6,332	
6BA-MXUA85			930	
3BA-AGH30W	[ALPHARD] [VELLFIRE]	2021	8,981	#1
3BA-AGH35W			820	
3BA-GGH30W			286	
3BA-GGH35W			106	
6AA-AYH30W			2,588	
3BA-NRE210	[COROLLA] [COROLLA TOURING]	2021	63	#1
3BA-NRE210W				
3BA-ZRE212			1,392	
3BA-ZRE212W				
6AA-ZWE211			4,604	
6AA-ZWE211W				
6AA-ZWE214	1,098			
6AA-ZWE214W				
6BA-MZEA12W	[COROLLA TOURING]	2021	456	#1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE	
3BA-NRE210H	[COROLLA SPORT]	2021	530	#1	
3BA-NRE214H			168		
6AA-ZWE213H			1,543		
6AA-AXAH52	[RAV4]	2021	255	#1	
6AA-AXAH54			1,597		
6BA-MXAA52			458		
6BA-MXAA54			5,145		
6LA-AXAP54	[RAV4 PHV]	2021	848	#1	
3BA-ARS220	[CROWN]	2021	69	#1	
6AA-AZSH20			2,712		
6AA-AZSH21			606		
6AA-GWS224			292		
6AA-ZVW51	[PRIUS]	2021	2,894	#1 and #2	
6AA-ZVW51			5,008	#2	
6AA-ZVW55			361	#1 and #2	
			863	#2	
6LA-ZVW52	[PRIUS PHV]	2021	377	#1 and #2	
			603	#2	
3DA-GDJ150W	[LANDCRUISER PRADO]	2021	666	#1	
3DA-GDJ151W			188		
3BA-TRJ150W			812		
			13		#1 and #3
			147		#3
6AA-AXVH70	[CAMRY]	2021	1,231	#1	
6AA-AXVH75			255		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3BA-NGX10	[C-HR]	2021	149	#1
3BA-NGX50			97	
6AA-ZYX11			746	
3DA-GDH303W	[GRAN ACE]	2021	7	#1
6AA-UWG60	[Century]	2021	6	#1
3BA-AGL20W	[RX300]	2021	1,089	#1
3BA-AGL25W			237	
6AA-GYL20W	[RX450h]	2021	620	#1
6AA-GYL25W			736	
6AA-GYL26W	[RX450hL]	2021	152	#1
6BA-MZAA10	[UX200]	2021	129	#1
6AA-MZAH10	[UX250h]	2021	1,429	#1
6AA-MZAH15			264	
ZAA-KMA10	[UX300e]	2021	207	#1
3BA-ASE30	[IS300]	2021	724	#1
3BA-GSE31	[IS350]	2021	140	#1
6AA-AVE30	[IS300h]	2021	1,029	#1
6AA-AVE35			130	
3BA-AGZ10	[NX300]	2021	291	#1
3BA-AGZ15			53	
6AA-AYZ10	[NX300h]	2021	567	#1
6AA-AYZ15			121	
6AA-AXZH11	[ES300h]	2021	672	#1
3BA-VXFA50	[LS500]	2021	137	#1
3BA-VXFA55			29	
6AA-GVF50	[LS500h]	2021	199	#1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-GVF55	[LS500h]	2021	127	#1
5BA-URZ100	[LC500]	2021	250	#1
6AA-GWZ100	[LC500h]	2021	32	#1
3BA-ASC10	[RC300]	2021	48	#1
3BA-GSC10	[RC350]	2021	31	#1
6AA-AVC10	[RC300h]	2021	76	#1
5BA-USC10	[RC F]	2021	25	#1
TOTAL			111,842	

#1: 105,221

#2: 10,106

#3: 160

#1 and #2: 3,632

#1 and #3: 13