

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5013	DATE	September 24, 2021
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	<p>[1] On the fuel tank, due to insufficient performance of heat resistance of the pump ring which is on top of the fuel tank, the pump rings may be deteriorated by exposure to heat from the engine and exhaust pipe. Therefore, continuous use may lead to deterioration, the pump rings may eventually crack and fuel leakage may occur, in the worst case, resulting in a fire.</p> <p>[2] On the fuel tank, due to inappropriate tighten true of the pump ring which is on the top of the fuel tank, the strength of the pump rings may decrease. Therefore, continuous use may lead to deterioration, the pump rings may eventually crack and fuel leakage may occur, in the worst case, resulting in a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-SE3P	Mazda「RX-8」	2008-2012	[1] [2] 8,193
CBA-SE3P		2008-2009	[1] [2] 230
DBA-GG3P	Mazda「Atenza」	2005-2007	[2] 1,782
CBA-GH5AP		2008-2009	[2] 242
DBA-GH5AP		2010-2012	[2] 120
CBA-GH5AS		2008-2009	[2] 373
DBA-GH5AS		2010-2012	[2] 178
CBA-GH5AW		2008-2009	[2] 955
DBA-GH5AW		2009-2012	[2] 418
			Total