

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5021	DATE	Sep.28 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some medium-duty trucks, the harness for the driver's seat belt buckle status sensor is improperly routed, and the harness can be pinched by the seat belt buckle during use. If this is repeated, the harness may be damaged and the seat belt warning light and alarm buzzer may operate erroneously.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FQ62F	「FUSO FIGHTER」	2019~2021	605
2KG-FK62F		2019~2021	1,699
2KG-FK62FY		2019~2021	293
2KG-FK62FZ		2019~2021	1,242
2KG-FK65F		2019~2021	1,559
2KG-FK65FY		2019~2021	166
2KG-FK65FZ		2019~2021	649
2KG-FK72F		2019~2021	1,427
2KG-FK72FY		2019~2021	257
2KG-FK72FZ		2019~2021	446
2KG-FK75F		2019~2021	190
2PG-FK62N		2019~2020	42
2PG-FK62NA		2019~2020	3
2PG-FK65N		2019~2020	13
2PG-FK65NA		2019~2020	5
2PG-FK72N		2019~2021	356
2PG-FK72NA		2019~2020	19
2PG-FK75N		2019~2020	11
2PG-FK75NA		2020	1
		TOTAL	8,983