VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai –3294	DATE	28 September, 2021
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG		
	(Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	there is a possibility that the screw connection of the		
	pressure input rod of the brake		
	booster was not carried out according to regulations.		
	As a result, the pressure input rod may become detached		
	from the brake booster over the running time of the		
	vehicle. If the pressure input rod is detached, it is not		
	possible to brake the vehicle using the brake pedal. The emergency braking function via the electric parking brake is still available without restriction.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3BA-992L30	911 Carrera	2020	2
	911 Carrera S	2020	3
	911 Carrera 4S	2020	1
		TOTAL	6