

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3295	DATE	September 29, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	In the brake servo connection rod, the tightening torque at the connection is insufficient due to improper assembly instructions at the time of manufacture. As a result, the bolted connection may loosen completely and detach from the brake servo connection rod, the brake may no longer functioning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-GYDLA	Audi A3 30T	2021	1
		Total	1