

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 0 2 7	DATE	Oct. 7. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the lower anchor bracket used with child restraint in the right rear seat as ISOFIX system, the width of fitting point on the bracket may not comply with the regulated size due to improper forming die used in supplier manufacturing process. In the worst case, the child restraint could not be installed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6AA-P15	N I S S A N K I C K S	2 0 2 0 ~ 2 0 2 1	35,111
		TOTAL	35,111