

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3291	DATE	October 8, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	The arm of the fuel gauge sender in the secondary tank chamber may get stuck on the fuel lines of the suction-jet pump due to inappropriate clearance, As a result, the remaining amount of fuel cannot be detected correctly by the fuel gauge and it may be displayed more than it actually is, and in the worst case, there is a risk of the vehicle cannot be driven due to running out of fuel while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-F3DNWF	Audi RSQ3	2021	297
3DA-F3DFGF	Audi Q3 35TDIq	2021	1,026
		Total	1,323