

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5028	DATE	12. Oct. 2021
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some engine crankcases have a pin hole due to casting defects, and the pin hole extends completely through to the engine oil passage. Because of this, engine oil may leak from the pin hole during vehicle operations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-VN09J	XVS950CU BOLT-R(A) XVS950CU BOLT(A)	2020~2021	324
		TOTAL	324