VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5033	DATE	October 14, 2021		
MANUFACTURER	Komatsu Ltd.				
DESCRIPTION OF DEFECT	Rainwater, etc. flow into the machine through the gap in the engine hood due to insufficient water entry evaluation and may be absorbed in the plastic battery relay case, and then may reach the switching section in the battery relay. If the machine is stored in a cold place in that status for a long period of time, the rainwater, etc. in the battery relay may freeze on the switching section. As a result, the switch contacts may not contact each other and may lose continuity, and the engine may fail to start.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
YDS-GD032	「GD675-6」	GD032-60003 - GD032-60893 January 15, 2015 – July 6, 2021		479
		-	TOTAL	479